

MARINER NEWS

BAYTRONICS
CORPORATION

TO: Service Departments

FROM: Walter E. Kaelin, V.P. Engineering

SUBJECT: Mariner 1500 Instruction and Service Manual
Chassis Wiring Diagram, Fig. 15


DATE: September 15, 1976

SEP 17 REC'D
OAKLAND, CALIF.
RECD. ON ABOVE DATE

The chassis wiring diagram (5-157041) represents graphically how wires and coaxial cables are connected to the circuit boards. Inadvertently, we crossed two coaxial cables leading from the low pass filter and Receiver RF (A2 board) to the IF Audio Board (A1). Note that the wiring diagram is error, not the actual wiring in the set. Enclosed are two copies of the corrected, revision B, wiring diagram. Please update service manuals as soon as possible.

Our TWX No. 910-338-0254

76107



MATERIALS

Fig. 15




Fig. 15

